2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

Page 1 of 1

## R44 SERVICE BULLETIN SB-93 R66 SERVICE BULLETIN SB-22

**DATE:** 6 June 2017

**TO:** R44-series & R66-series Owners, Operators, and Maintenance Personnel

**SUBJECT:** Horizontal Stabilizer Nutplates

**ROTORCRAFT AFFECTED:** R44-series & R66-series Helicopters equipped with C044-1 horizontal stabilizer assemblies S/N 7740 thru 8519 and 8690 thru 8719.

**TIME OF COMPLIANCE:** Within next 10 flight hours.

**BACKGROUND:** An operator noticed signs of loose vertical stabilizer attach bolts (fretting debris) during preflight inspection. Subsequent investigation revealed three cracked MS21086L4 nutplates where the C042-1 & C043-1 vertical stabilizers attach to the C044-1 horizontal stabilizer (there are eight total nutplates, four per vertical stabilizer). All of the cracked nutplates are from a single manufacturer's lot which were used on the stabilizer S/Ns above. This bulletin requires verifying the integrity of the nutplates.

## **COMPLIANCE PROCEDURE:**

- 1. Determine C044-1 horizontal stabilizer serial number from data plate at inboard rib. If serial number is not in the affected range, no further action is required.
- 2. For affected stabilizer assemblies, remove torque stripe from eight NAS6604-6 bolts and eight C130-9 spacers securing C042-1 (upper) & C043-1 (lower) vertical stabilizers to C044-1 horizontal stabilizer.
- 3. Apply 185 inch-pounds torque to each bolt, and observe rotation. If any bolt rotates more than one flat (1/6 of a turn), remove vertical stabilizer(s) and visually inspect corresponding nutplate for cracks. Contact RHC Technical Support with location of any cracked nutplate(s) and C044-1 horizontal stabilizer serial number. Replace any cracked nutplate(s) prior to further flight. Reinstall vertical stabilizer(s) and torque attach bolts to 185 inch-pounds.
- 4. Apply torque seal from bolt head across spacer to vertical stabilizers, eight places.
- 5. Make appropriate maintenance entry records.

## **APPROXIMATE COST:**

Parts: None.

Labor: Approximately 0.5 man-hour.

THE DESIGN ENGINEERING ASPECTS OF THIS BULLETIN HAVE BEEN SHOWN TO COMPLY WITH APPLICABLE FEDERAL AVIATION REGULATIONS AND ARE FAA APPROVED.