2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

Page 1 of 2

R44 SERVICE BULLETIN SB-86

DATE: 03 July 2013

TO: R44 & R44 II owners, operators, and maintenance personnel

SUBJECT: Rotor RPM Sender Magnets

ROTORCRAFT AFFECTED: R44 helicopters S/N 0001 thru 2310, R44 II helicopters S/N 10001 thru 13519, spare C006 main rotor gearbox assemblies, spare C908-1 yoke assemblies, and spare 102MG11 magnets (alternate P/N 102MG11BP). B570-1 magnets with black epoxy fillet are unaffected (see Figure 1).

TIME OF COMPLIANCE: Within next 100 flight-hours or by 31 October 2013.

BACKGROUND: RHC received a report that a MRGB yoke assembly's 102MG11 magnet came out of its housing during flight and activated the low-rotor RPM warning system. This bulletin requires applying additional adhesive to affected magnets.

COMPLIANCE PROCEDURE:

- Refer to Figure 2. At C908-1 yoke assembly, if a yellow dot is painted on the outboard surface of both 102MG11 magnet housings, the requirements of this bulletin have been complied with. Proceed to step 8.
- 2. If gearbox is installed, remove tailcone cowling.
- Refer to Figure 3. Rotate blades as necessary. Press in on magnet with finger to
 ensure magnet is completely seated in magnet housing. Apply B270-10 adhesive to
 create a continuous fillet between magnet and magnet housing. Repeat for second
 magnet.
- 4. Allow adhesive to cure for a minimum of 4 hours.
- 5. Wipe off adhesive from magnet exterior (adhesive will be drawn into space between magnet and housing and will be dry in this location, but wet on the exterior.)
- 6. Paint a yellow dot on outboard surface of both magnet housings.
- 7. If applicable, install tailcone cowling.
- 8. Make appropriate maintenance record entries.

Approximate Cost:

Parts: B270-10 adhesive (refer to MM § 1.480). B270-10.5ml (0.5 ml; \$3.50) and

B270-10 (50 ml; \$74.00) quantities are available from RHC.

Labor: 1.0 man-hour, excluding adhesive cure time.




FIGURE 3

THE DESIGN ENGINEERING ASPECTS OF THIS BULLETIN HAVE BEEN SHOWN TO COMPLY WITH APPLICABLE FEDERAL AVIATION REGULATIONS AND ARE FAA APPROVED.