

SERVICE LETTER #4

DATE: 07 September 1994

TO: All R44 Owners and Operators

SUBJECT: Engine breather coupling

ROTORCRAFT AFFECTED: R44 Helicopter S/N's 0001 thru 0098

BACKGROUND: RHC has received reports of the A729-10 tube, coupling the engine breather tube to the engine, breaking and allowing oily engine vapors to coat the surrounding area. A new, thicker walled tube made from a more durable material is now available.

COMPLIANCE PROCEDURE:

- 1) Order from RHC one A729-10 Rev. K or later tube.
- 2) Remove existing tube and install new Rev. K or later tube being careful to minimize misalignment and stress on the tube.

Approximate Cost:

PARTS: No charge

LABOR: 0.3 manhours

