2901 Airport Drive, Torrance, California 90505

Phone(310) 539-0508 Fax (310) 539-5198

R44

Page 1 of 1

SERVICE LETTER SL-35A

DATE: 18 March 2008 **REV A:** 25 March 2009

TO: R44 II Owners, Operators, and Service Centers

SUBJECT: Servo Plugs

TIME OF COMPLIANCE: The U.S. FAA has issued Airworthiness Directive (AD) 2009-02-03 in response to reports of engine power loss due to loose fuel injection servo plugs. The AD supersedes ADs 2008-06-51 and 2008-08-14. R44 II helicopters are equipped with RSA-10 series fuel injection servos, also known as fuel control units, which are affected by the AD.

COMPLIANCE PROCEDURE:

Prior to further flight, follow AD 2009-02-03 instructions. The AD may be downloaded from: www.faa.gov/aircraft/safety/alerts.