

SERVICE LETTER #33

Date: May 18, 1989

To: All R22 Owners and operators of helicopters specified below only

Subject: Aeroquip Corporation Bulletin No. 001

Rotorcraft Affected: R22 Helicopters S/N 002-820

Background: Aeroquip Corporation has issued a Service Bulletin No. 001 recalling their 601 type flexible hoses, with cure dates between April 1984 (A2Q84) through May, 1988 (A2Q88). Robinson Helicopter was supplied a limited number of these hose assemblies which were affected by the Bulletin. The helicopters listed below likely had affected hoses installed between the carburetor and gascolator at the factory. Other helicopters may have had flexible fuel or oil lines; replaced during field maintenance or during overhaul.

---

Compliance Procedure

Inspect per enclosed Aeroquip Corporation Bulletin No. 001.

HELICOPTERS LIKELY AFFECTED WITH AEROQUIP 601  
FUEL HOSES INSTALLED AT RHC

Serial Numbers: 667 through 673

Serial Numbers: 768 Through 794