

R66 SERVICE BULLETIN SB-02

DATE: 27 October 2011

TO: R66 owners, operators, and maintenance personnel

SUBJECT: Placards and Markings

ROTORCRAFT AFFECTED: R66 helicopters S/N 0004 thru 0051, 0053 thru 0058, 0060, 0064 thru 0066, and 0071.

TIME OF COMPLIANCE: Within next 150 flight hours or by 31 January 2012, whichever occurs first.

BACKGROUND: Some placards and markings were revised to comply with foreign certification requirements. Affected aircraft require one or more revised placards to match the required placards listed in the 1 September 2011 revision to the R66 Pilot's Operating Handbook.

COMPLIANCE PROCEDURE:

1. a. For R66 helicopters S/N 0004 thru 0015: Order one KI-208-1 kit and install per [kit instructions](#). Kit includes placards, updated pilot's checklist, & instructions.
b. For R66 helicopters S/N 0016 and subsequent (see Rotorcraft Affected): Order one KI-208-2 kit and install per [kit instructions](#). Kit includes placards, updated pilot's checklist, & instructions.
2. Update helicopter's R66 Pilot's Operating Handbook (POH) to include 1 September 2011 revision (or subsequent). R66 POH updates are automatically mailed to Subscription J-, K-, and L-Class holders. The POH should not be updated until the placards have been installed.
3. Make appropriate maintenance record entries.

Approximate Cost:

Parts: No charge for KI-208-1 or KI-208-2 kits if ordered by 31 January 2012.
Reference helicopter serial number.

Procure parts from any R66 Dealer or Service Center, or order directly from assigned [RHC Customer Service Agent](#) via email, fax, or phone.

Labor: 1.0 man-hour.