

R22 SERVICE LETTER SL-85

R44 SERVICE LETTER SL-71

R66 SERVICE LETTER SL-32

DATE: 11 March 2020

TO: R22, R44 & R44 II, and R66 owners, operators, and maintenance personnel

SUBJECT: Kannad ELT Service Bulletin

ROTORCRAFT AFFECTED: Helicopters equipped with optional “AF-Compact” model Emergency Locator Transmitter (ELT) manufactured by Kannad (Orolia).

BACKGROUND: Kannad (Orolia) has issued Service Bulletin S1840502-25-01, which affects Kannad P/N S1820512-01 Self-stripping Straps. In 2019, some straps were manufactured with 2.7 mm diameter buckles; the correct buckle is 4 mm diameter. Contact Orolia (www.orolia.com, or support@orolia.com) for Service Bulletin information.

COMPLIANCE PROCEDURE:

Open applicable access door and measure Kannad P/N S1820512-01 Self-stripping Strap buckle per figure below. If buckle is 2.7 mm, refer to replacement procedure in Kannad Service Bulletin S1840502-25-01.

