

R22 SERVICE LETTER SL-88

DATE: 11 March 2020

TO: R22 Owners, Operators, and Maintenance Personnel

SUBJECT: A792-5 Dual Tachometer

BACKGROUND: Supply of A792-4 dual tachometers is limited. A new A792-5 dual tachometer will supersede A792-4 tachometers and is functionally interchangeable. A B792-1 (adapter) harness assembly is required to connect A792-5 tachometers to airframe wiring on earlier R22s.

COMPLIANCE PROCEDURE:

When replacing an A792-4 tachometer with an A792-5 tachometer, install B792-1 dual tachometer harness assembly between tachometer & airframe harness, and tighten two screws on both connectors. Secure B792-1 harness as required with ty-raps.