2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

Page 1 of 2

**R22 SERVICE LETTER SL-96** 

**R44 SERVICE LETTER SL-85** 

**R66 SERVICE LETTER SL-43** 

**DATE:** 16 March 2023


**TO:** R22-series, R44-series, & R66 Owners, Operators, & Maintenance Personnel

**SUBJECT:** Tail Rotor Static Balance Equivalent Tool

**BACKGROUND:** Current RHC Maintenance Manuals' (MM) Tail Rotor Static Balance sections specify "Anderson 20 (or equivalent) Balancing Stand". An acceptable equivalent is described on page 2.

## **COMPLIANCE PROCEDURE:**

See page 2.



## NOTE

Ensure tail rotor assembly has clearance to angles, counterweight & table. Perform static balancing in a draft-free environment.