2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

Page 1 of 1

## **R44 SERVICE LETTER SL-89**

**DATE:** 9 February 2024

**TO:** R44-series Owners, Operators, and Maintenance Personnel

**SUBJECT:** Symmetrical Horizontal Stabilizer Retrofit Kit

**BACKGROUND:** A retrofit kit is available to install the <u>new symmetrical horizontal</u> stabilizer on p/n C023-1, -2, -3, -4, -14 & -15 revision AV & prior tailcones.

## **COMPLIANCE PROCEDURE:**

As desired, order KI-285-2 kit and replace C044-1 stabilizer per kit instructions.

KI-285-2 is presently approved for installation on all R44-series helicopters, except for those registered in the following countries:

- EASA member states
- China
- India
- Israel
- Japan
- United Kingdom
- Russia
- CIS member states with the IAC AR.

Foreign validations are ongoing and this SL will be revised as additional approvals are received.

## **APPROXIMATE COST:**

Parts: KI-285-2 kit, \$3,600 if ordered by 31 December 2024. Must reference helicopter model and serial number. Stabilizer assembly supplied unpainted, with primer only. For assembly painted white add \$375. For assembly painted custom color add \$750.

Labor: 8 labor-hours.