

ROBINSON HELICOPTER COMPANY
24747 CRENSHAW BLVD.
TORRANCE, CA 90505

SERVICE LETTER #4

DATE: July 22, 1980

SUBJECT: Battery Ground Strap

ROTORCRAFT AFFECTED: Model R22 S/N 0002,0006 through 0016,0018 through 0020,
0022 through 0032

TIME OF COMPLIANCE: At next inspection

MATERIALS REQUIRED: A780-2 cable assembly battery ground
Mechanics hand tools

INSTALLATION PROCEDURE:

1. Remove screws to provide battery access.
2. Disconnect existing battery cable and ground straps. Remove bolt securing existing straps to fuselage.
3. Install new flexible cable assembly after making sure the grounding metal is clean. Reinstall battery and box.
4. Make proper log book entry in compliance with RHC service letter #4.

DISPOSITION OF REMOVED PARTS: Discard A213 straps at removal site.