

Robinson Helicopter Company

24747 CRENSHAW BLVD., TORRANCE, CA 90505 TELEPHONE (213) 539-0508

SERVICE LETTER #10

Date: August 11, 1981

To: All Owners and Operators of Robinson R22 Helicopters

Subject: Engine Idle Speed Limitations

Rotorcraft Affected: R22 Serial No. 0002 through 0232

Time for Compliance: Immediate

Background: The tachometer must be placarded to indicate "Avoid Idle 60-70%". This is to prevent undesirable vibrations that can occur in the tail of the helicopter during idle. A placard decal is enclosed to install on your tachometer.

Decal Installation Procedure

- 1) Carefully peel the decal from its backing using a razor blade. Care must be taken not to touch the decal's adhesive backing as it may appear illegible when installed
- 2) Place the decal across the lower glass face of the tachometer and press firmly.

By: *Frank H. Linder*
Service Department

P.S. If your ship has been sold, please forward to new owner.