

**R66 SERVICE LETTER SL-36**

**DATE:** 21 August 2020

**TO:** R66 Owners, Operators, & Maintenance Personnel

**SUBJECT:** Firewall Drain Tube

**ROTORCRAFT AFFECTED:** R66 Helicopters S/N 0003 thru 0971.

**BACKGROUND:** RHC has received reports of corrosion on the engine gearbox housing. On affected helicopters, water on the horizontal firewall can drain onto the engine. A kit is available for installing a tube which diverts water draining from the firewall away from the engine.

---

**COMPLIANCE PROCEDURE:**

Refer to R66 Illustrated Parts Catalog Figure 71-19.

Order one KI-258-1 Firewall Drain Installation Kit if helicopter is equipped with a G727-1 (aluminum) engine vent tube, or

order one KI-258-2 Firewall Drain Installation Kit if helicopter is equipped with an A785-36 (orange flexible) engine vent hose.

Install per kit instructions.