

26 March 2024

**Tail Rotor Blade Replacement Policy for**  
**R22 SB-120 / R44 SB-112 / R66 SB-41 (latest revision)**

Orders for replacement tail rotor blades are limited to 5 matched sets (10 blades). Different part numbers are permitted, such as two A029-2 & six C029-3 & two F029-1.

For affected blades only, two ordering options are available:

**Option 1 - Return blade Data Plates before submitting order:**

- Send [Customer Support](#) well-focused, digital photos of each associated legible data plate & tail rotor blade; indicate S/N on blade as shown in example photo at bottom.
- Remove legible data plates, attach plates to a completed [Component Return Authorization](#) form, and return plates & form to RHC.
- Returned data plates will be inspected and submitted photos reviewed.
- After inspection and verification of eligibility per relevant SB, Customer Support will advise final cost.

**-OR-**

**Option 2 - Order prepaid replacement blades from [Customer Support](#):**

- When submitting order, include well-focused, digital photos of each associated legible data plate & tail rotor blade; indicate S/N on blade as shown in example photo at bottom.
- For each blade ordered, customer will be charged applicable Service Bulletin price plus a \$500 data plate core charge.
- After new blades are installed, remove legible data plates, attach plates to a completed [Component Return Authorization](#) form, and return plates & form to RHC.
- Returned data plates will be inspected and submitted photos reviewed.
- After inspection and verification of eligibility per relevant SB, core charge will be refunded along with any applicable warranty credit.

**Example photos:**

